

EXCAVATED DIRT STOCKPILES

Image from page C020 of the 7/31/2017 plans showing the two soil stockpiles from excavation for the deck.




Image from page C300 of the 7/21/2017 plans showing the two existing stockpiles remaining and the regrading of the bowl (non-dashed lines are where regrading is occurring).




Image from page C200 of the 7/31/2017 plans showing the remaining asphalt lot and the asphalt road being added to connect the lot.

